

SCAC06

LVDT SIGNAL CONDITIONER

Features

- Push-button auto-calibration
- Analog voltage or current loop output
- Supports all standard AC LVDTs, RVDTs, and VR half-bridge sensors
- Master/slave excitation synchronization
- DIN35-rail mountable
- Color-coded terminal blocks

User Selectable Features

- 0-5V DC, 0-10V DC, 0.5-4.5V DC, $\pm 5V$ DC, $\pm 10V$ DC or
- 4-20 mA output
- 1.5Vrms or 3.0Vrms sensor excitation
- 2.5, 5, 7.5, or 10 kHz excitation frequency



The SCAC06 single-channel push-button calibrated signal conditioner from ABEK SENSORS, with a 9 - 30V DC supply, supports any standard LVDT, RVDT and half-bridge LVRT position sensor. Multiple voltage and current outputs are available simultaneously.

The SCAC06 is housed in a DIN rail-mounted plastic case with different colored terminals for differentiation and to prevent wiring errors. Two front panel calibration buttons allow calibration of the LVDT or RVDT position transducer for any range segment within the full travel range.


The SCAC06 also provides functions such as excitation voltage, excitation frequency selection, adjustment of different output bandwidths, and LVDT fault indication.

Specifications


Parameter	Description
Input Voltage:	9-30V DC (24V (nominal), 90mA (max))
LVDT Excitation Voltage:	1.5 V, 3.0 V AC rms (selectable)
LVDT Excitation Frequencies	2.5kHz、5kHz、7.5kHz、10kHz(selectable)
LVDT AC Output Range:	50 mVrms to 5.5V rms at LVDT full scale position
Output:	0-5V、0-10V、±5V、±10V、4-20mA (selectable)
Output bandwidth (-3dB):	1Hz、10、100、500 Hz (selectable) , 500 Hz (Max)
Operating Temperature:	-20°C to +85°C
Noise and Ripple:	<1 mV rms (voltage output); 10 µA rms (current loop output)

Wiring


LVDT / RVDT Hookup:



LVRT Half Bridge Hookup:




DIP SWITCH SETTINGS



Switches shown in factory default position.


Calibration method

1. Press and hold both buttons for 3 seconds. The red PWR LED will begin blinking.




Hold for 3 Seconds

2. Move the LVDT core to NULL position by observing the + / N / - LEDs. T When the Green N light illuminates, this is the center of the LVDTs measuring range.




Core at the null point


Green light illuminates




3. Attach the measured object to the core. For best accuracy, the center of the object's range of motion aligns with the NULL position.
4. Move measured object to its minimum position and press the ZERO button setting the point of lowest output.




Core at desired ZERO point



5. Wait for + / N / - LEDs to stop blinking.
6. Move measured object to its maximum position and press the FULL SCALE button. The PWR LED will remain lit. The unit is now calibrated.



Core at desired FULL SCALE point



Dimensions

